

### Service Bulletin Compliance Record

Registration: N 199 CH A/C Make: Vans A/C Model: RV-12 A/C Serial No. 120818

Service Bulletin No.	Effective Date	Subject	Compliance Due Date Hours/Other	Date of Compliance	Airframe Total Time	One Time or Recurring	Next Compliance Due Date Hours/Other	Authorized Signature, Certificate, Type and Number
SB-14-11-03	11/3/14	Wing Skin to Spar Rivet Wear		1/7/2020	474.2	Re		Shapel Myers 3231362 A:P
Method of Compliance/Remarks: VISUAL								
SB-18-03-06	3/6/2018	Throttle Return Spring		1/7/2020	474.2	Re		Shapel Myers 3231362 A:P
Method of Compliance/Remarks: C/W P/N Spring - 00002-1 (Vans P/N)								
SB-16-08-01	8/1/2016	Stabilator Bearing Insp		1/7/2020	474.2	Re		Shapel Myers 3231362 A:P
Method of Compliance/Remarks: C/W by inspection								
SB-16-08-24	8/24/2016	Loose engine mount bracket		1/7/2020	474.2	Re		Shapel Myers 3231362 A:P
Method of Compliance/Remarks: C/W by inspection								
SB-16-05-23	5/23/2016	Nose fork inspection		1/7/2020	474.2	Re		Shapel Myers 3231362 A:P
Method of Compliance/Remarks: C/W by inspection								
N 17-12-08	12/08/17	CANOPY LATCH UPGRADE		01/30/20	513.60	ONE TIME	N/A	B-U-D A:P 3384712
Method of Compliance/Remarks: C/W BY INSTALLING UPGRADE KIT.								
SB 16-05-23	05/23/16	WD-1230 NOSE FORK CRACKS		03/15/20	580.0	REC.	605.0	B-U-D A:P 3384712
Method of Compliance/Remarks: C/W BY INSPECTING NOSE FORK. NO CRACKS FOUND								
SB 20-01-17	02/05/20	SAFETY WIRE ENGINE PLUGS		03/15/20	580.0	ONE TIME	N/A	B-U-D A:P 3384712
Method of Compliance/Remarks: C/W BY SAFETY WIRING ENGINE PLUGS								
N 18-07-12	07/12/18	CHANGE TO HIGH PRESS AUX FUEL PUMP	N/A	04/17/20	607.8	ONE TIME	N/A	Shapel Myers
Method of Compliance/Remarks: C/W BY INSTALLING ES40135 ELECTRIC FUEL PUMP								

### Service Bulletin Compliance Record

Registration: N199CH A/C Make: VAN'S A/C Model: RV-12 A/C Serial 120818  
 No. \_\_\_\_\_

Service Bulletin No.	Effective Date	Subject	Compliance Due Date Hours/Other	Date of Compliance	Airframe Total Time	One Time or Recurring	Next Compliance Due Date Hours/Other	Authorized Signature, Certificate, Type and Number
SB 16-05-23	05/23/16	"NOSE FORK CRACK INSP."	628.2	04/28/20	620.2	REC.	645.2	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND								
SB 16-05-23	05/23/16	"NOSE FORK CRACK INSP."		05/17/20	665.1	REC.	691.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND								
SD 00001	05/14/20	"PITCH TRIM ASSY INSP."	669.2	05/19/20	669.2 688.2	REC.	1000.0	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSP. ES MST5-86 <sup>BU</sup> T3-7A-2 IS INSTALLED. SHAFT IS STRAIGHT. MOTOR DUE FOR REPLACEMENT @ 1000 HRS								
SB 16-05-23	05/23/16 05/27/20	"NOSE FORK CRACK INSP"	691.1	05/27/20	691.1	REC.	716.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS WERE FOUND								
SB 16-08-24	09/06/16	"LOOSE ENG. MNT. BRKT. RVTS."		08/01/20	787.1	REC.	887.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO LOOSE RIVETS FOUND.								
SB 16-08-01	10/01/16	"STABILATOR BEARNG INSP."		08/01/20	787.1	REC.	887.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO INTEREERANCE FOUND.								
SB 16-05-23	05/23/16	"NOSE FORK CRACKS"		08/01/20	787.1	REC.	882.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND.								
SB 14-11-03	12/31/14	"WING SPAR RIVET WEAR"		08/01/20	787.1	REC.	887.1	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO LOOSE RIVETS FOUND.								
SB 16-05-23	05/23/16 08/13	"NOSE FORK CRACKS"		08/13/20	797.9	REC.	822.9	BUND AIP 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND.								

### Service Bulletin Compliance Record

Registration: N199CH A/C Make: VAN'S A/C Model: RV-12 A/C Serial No. 120818

Service Bulletin No.	Effective Date	Subject	Compliance Due Date Hours/Other	Date of Compliance	Airframe Total Time	One Time or Recurring	Next Compliance Due Date Hours/Other	Authorized Signature, Certificate, Type and Number
SB-16-05/23	05/23/16	"NOSE FORK CRACKS"	822.9	08/31/20	821.1	REC	846.1	BUND A3P 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND.								
SB 00005	08/24/20	"EXHAUST PIPE CRACKS"		08/31/20	821.1	REC	846.1	BUND A3P 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND								
SB 16-05-23	05/23/16	"NOSE FORK CRACKS"	846.1	09/07/20	843.4	REC	868.4	BUND A3P 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND.								
SB 00005	08/24/20	"EXHAUST PIPE CRACKS"	846.1	09/07/20	843.4	REC	868.4	BUND A3P 3384712
Method of Compliance/Remarks: C/W BY INSPECTION. NO CRACKS FOUND								
SB 00005	08/24/20	"EXHAUST PIPE CRACKS"	868.4	09/16/20	858.0	ONE TIME	N/A	BUND A3P 3384712
Method of Compliance/Remarks: C/W BY INSTALLING NEW EXH. PIPES								
16-05/23 SB 00005	5/23/16 10/01/20	"NOSE FORK CRACKS"		10/01/20	864.0	REC	889.0	Phil/John
Method of Compliance/Remarks: C/W INSPECTION. NO CRACKS FOUND								
SB-00059	4/29/23	CANOPY LATCH BLOCK		4/29/23	1818.7	ONE TIME	NA	Phil/John
Method of Compliance/Remarks:								
SB 00017	4/29/23	#1 CYLINDER EXHAUST SPRINGS		4/29/23	1818.7	ONE TIME	NA	Phil/John
Method of Compliance/Remarks:								
31300067	5/9/23	STABILATOR MASS BALANCE REINFORCEMENT		5/9/23	1827.5	ONE TIME	NA	Phil/John
Method of Compliance/Remarks:								

